JUN 0 2 MG SO

03500.017296

COFFE A

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: David H. Bollinger
TAKEHIKO KAWASAKI)	
	:	Group Art Unit: 3653
Appl. No.: 10/656,504)	
	:	Confirmation No.: 8342
Filed: September 8, 2003)	
	:	
For: DOUBLE FEED DETECTION METHOD)	
AND DOUBLE FEED DETECTION	:	Certificate
APPARATUS OF SHEET MATERIALS)	JUN 08 2005
	:	
U.S. Patent No.: 6,866,263 B2)	of Correction
	:	
Issued: March 15, 2005)	June 2, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

06/03/2005 YPOLITE2 00000104 6866263

01 FC:1811

100.00 OP

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl Attorney for Patentee Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

Form #33 - 2 -

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,866,263 B2

DATED

March 15, 2005

INVENTOR(S) :

TAKEHIKO KAWASAKI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 37, "an vibration" should read --a vibration--. Line 39, "an vibration" should read --a vibration--.

COLUMN 7:

Line 62, "BaTiB₃," should read --BaTiO₃,--.

COLUMN 8:

line 42, "an one-" should read --a one- --.

COLUMN 9:

Line 14, "preciously" should read --previously--.

COLUMN 11:

Line 45, "he voltage" should read -- the voltage--.

Line 47, "so determined" should read -- also determined--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. <u>6,866,263 B2</u>

No. of add'l. copies @ 30¢ per page



JUN 9 2005

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,866,263 B2

DATED

March 15, 2005

INVENTOR(S) :

TAKEHIKO KAWASAKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 30, "stropped" should read --stopped--. Line 40, "allows" should read --allows that--. Line 43, "thus" should read --and thus--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,866,263 B2

No. of add'l. copies @ 30¢ per page

o Landa

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,866,263 B2

DATED

March 15, 2005

INVENTOR(S) :

TAKEHIKO KAWASAKI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 37, "an vibration" should read --a vibration--.

Line 39, "an vibration" should read --a vibration--.

COLUMN 7:

Line 62, "BaTiB₃," should read --BaTiO₃,--.

COLUMN 8:

line 42, "an one-" should read --a one- --.

COLUMN 9:

Line 14, "preciously" should read --previously--.

COLUMN 11:

Line 45, "he voltage" should read -- the voltage--.

Line 47, "so determined" should read -- also determined--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>6,866,263 B2</u>

Form PTO 1050 (Rev. 3-82) (Form#30)

TUN' 8 FAAR

Stable Ouldi

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,866,263 B2

DATED

March 15, 2005

INVENTOR(S) :

TAKEHIKO KAWASAKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 30, "stropped" should read --stopped--. Line 40, "allows" should read --allows that--. Line 43, "thus" should read --and thus--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,866,263 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) (Form#30)